
## Preliminary Hand-Held Air Monitoring Locations | ITC Deer Park Tank Fire

## Reading Date

3/27/2019 7:00:00 PM to 3/27/2019 8:00:00 PM



## Recent Benzene Detections

Location Category	Reading Date	Concentration
Division B	3/27/2019 19:33:25	0.33 ppm
Division E	3/27/2019 19:43:29	2.90 ppm
	3/27/2019 19:39:57	11.95 ppm
	3/27/2019 19:37:26	4.43 ppm
	3/27/2019 19:28:01	1.12 ppm
	3/27/2019 19:25:04	0.60 ppm
	3/27/2019 19:22:19	0.91 ppm
	3/27/2019 19:21:22	0.05 ppm
	3/27/2019 19:19:10	1.10 ppm
	3/27/2019 19:14:55	1.49 ppm
	3/27/2019 19:12:50	0.43 ppm
	3/27/2019 19:12:15	16.70 ppm
	3/27/2019 19:07:48	0.24 ppm
Impacted Tank Farm	3/27/2019 19:50:05	0.73 ppm

Not all real time data on this website have undergone full QA/QC (quality assurance/quality control) analysis. It has been provided expeditiously to regulatory agencies and on-site contractors for informational purposes only